



Division of Waste Management
Office of Environmental Remediation
1356 Hansford Street
Charleston, WV 25301
(304) 558-2508
(Fax) (304) 558-3998

West Virginia Department of Environmental Protection

Bob Wise Governor Stephanie R Timmermeyer Secretary

23 January 2004

Dominic T. O'Connor PE Remedial Project Manager Code EV23DO Naval Facilities Engineering Command Atlantic Division 1510 Gilbert Street Norfolk, Virginia 23511-2699

SUBJECT:

Allegany Ballistics Laboratory

Work Plan Addendum for Phase IV Investigations

At SWMUs 2 and 27A and Removal Activities at SWMU 37II

Dear Mr. O'Connor:

The West Virginia Department of Environmental Protection/Division of Land Restoration has reviewed the *Draft Work Plan Addendum for Phase IV Investigations At SWMUs 2 and 27A and Removal Activities at SWMU 37II* for the Allegany Ballistics Laboratory Superfund Site Rocket Center, West Virginia and provides the following comments.

- Page 2-1 second paragraph: There is an extra parenthesis at the end of the second sentence.
- 2. Page 2-2 second paragraph: The analytical results identified in the paragraph were collected through a procedure that is well known to distort the actual results when compared the permanent monitoring wells. This paragraph should be qualified.
- 3. Page 2-2; SWMU 2-Former Hazardous Waste Storage Area II; The former hazardous waste storage area was a RCRA subtitle B permitted unit identified in the facilities RCRA permit. This area was not identified as a satellite accumulation area. Further, the reference to SWMU 24 should be clarified. There is a series of SWMU 24 throughout the facility. The current wording implies only one location provided waste to the former hazardous waste storage pad.

4. Page 2-2; SWMU 2-Former Hazardous Waste Storage Area II: The discussion in the last paragraph is misleading and should be clarified. There has been no documentation provided to date that analytical methods were utilized to verify that the sumps contents were not impacted prior to the release. During historic discussions, it was identified that the stormwater was visually examined prior to release to the ground surface. Please include the historic data or clarify the discussion.

If you have any questions or need additional clarification, please contact me at (304) 558-2508 or Email tbass@wvdep.org.

Thomas L. Bass

Environmental Resource Specialist Office of Environmental Remediation

Superfund Group

cc: Donald Martin, WVDEP Todd Richardson, USEPA Lou Williams, NAVSEA John Aubert, NAVSEA